

Manhole Inspection Summary

Manhole # S51M__003MH

Printed On: 12/16/2008

Page 1 of 4

Inspection Is Incomplete Rating: **3) Fair**

Record Plat: **51M** Node: **003** Status: **Found**

Insp Date: **4/14/08 9:39 AM**

Incomplete Comments

Crew: **danny**
Inspector: **jjoiner**
Firm: **ATS**

Location Address: **820 fait-hudson**

Cross Street: **s belnord av**

Manhole Type: **Junction** Location: **Alley**

Ground Conditions: **Dry**

Prev. Rehab Weather: **Dry**

Subject To Ponding: **None**

Comments **aaa**

Cover Shape: **Circular** Diameter: **25.** (in.) Length: **0** (in.) Dist A/B Grade: **0** (in.)
5

Type: **Sanitary** Condition: **Sound** Cover Material: **Cast Iron**

Properties: Bolted Vented Water Tight Water Tight Insert

Frame Offset: **0** (in.) Condition: Sound Cracked Leaks

Chimney / Frame Adjustment Exists Material: Parged Height: **0** (in.)

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar Roots Wall

Corbel Material: **Brick** Parged Type: **Concentric/Eccentric**

Condition: Sound Cracked Root Intrusion **Loose Brick** Deteriorated

Infiltration: None Joint Cracks Mortar Roots Wall

Barrel Material: **Brick** Parged

Shape: **Circular** Diameter: **48** (in.) Length: **0** (in.)

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar Roots Wall

Bench Exists Material: **Brick** Parged

Condition: Sound Cracked Root Intrusion Deteriorated Leaks Debris

Channel Material: **Block** Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth: **0**

Condition: Sound Cracked Root Intrusion Deteriorated Leaks Debris

Steps Count: **5** Missing: **0** **Corroded**

Surcharge Evidence Of Surcharge Depth: **0** (ft.) Active Surcharge Present

Location View



Top View



Defect 2



steps

Defect 1



corbel

Manhole Inspection Summary

Manhole # S51M__003MH

Printed On: 12/16/2008

Page 3 of 4

8 in. Circular Gravity Sewer
Pipe Out @ 12 O'Clock

12 O'Clock Outflow



Pipe Height: **0** (in.) Direct
Pipe Material: **Clay** Pipe Lined
Invert Depth: **8.63** (ft.) Flow Characteristics: **Slow**
Deposits: None Mud Sludge Debris Grease
Silt Depth: **0** (in.) Deposits Extent:
Infiltration: **None** Pipe Seal Cond: **Unknown**

Drop: **None**

Connects To: **Manhole**
 Possible Illicit Connection

8 in. Circular Gravity Sewer
Pipe In @ 3 O'Clock

3 O'Clock Inflow



Pipe Height: **0** (in.) Direct
Pipe Material: **Clay** Pipe Lined
Invert Depth: **8.46** (ft.) Flow Characteristics: **Slow**
Deposits: None Mud Sludge Debris Grease
Silt Depth: **0** (in.) Deposits Extent:
Infiltration: **None** Pipe Seal Cond: **Unknown**

Drop: **None**

Connects To: **Manhole**
 Possible Illicit Connection

Manhole Inspection Summary

Manhole # S51M__003MH

Printed On: 12/16/2008

Page 4 of 4

8 in. Circular Gravity Sewer
Pipe In @ 9 O'Clock

9 O'Clock Inflow



Pipe Height: **0** (in.) Direct

Pipe Material: **Clay** Pipe Lined

Invert Depth: **8.50** (ft.) Flow Characteristics: **Slow**

Deposits: None Mud Sludge Debris Grease

Silt Depth: **0** (in.) Deposits Extent:

Infiltration: **None**

Pipe Seal Cond: **Unknown**

Drop: **None**

Connects To: **House connection / Service line**

Possible Illicit Connection